

General Environmental Incident Summary

Incident: 3666 **Date/Time Notice:** 2/27/2015 1255 **DEM Incident No:**
Responsible Party: Key Energy Services
Date Incident: 2/27/2015 **Time Incident:** 0130 **Duration:** 5 minutes
County: Dunn **Twp:** 141 **Rng:** 96 **Sec:** 1 **Qtr:** NE NE
Lat: 47.05352 **Long:** -102.79950 **Method:** Interpolation from map
Location Description: This is a brine water injection site by the corner of Highway 22 and 25th Street SW in Dickinson.ND.
Submitted By: Todd Salsgiver **Affiliation:** ERTS
Address: 6001 Cochran Rd.Suite 300
City: Solon **State:** OH **Zip:** 44139

Received By:

Contact Person: Daniel Gibson
6 Desta Dr
Midland, TX 79705

Distance Nearest Occupied Building: 2 Miles **Release Contained:** No

Type of Incident: Pipeline Leak

Description of Released Contaminant: produced brine water

Volume Spilled: 60.00 barrels **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** No

Cause of Incident:

Flowline malfunction. Brine water for well injection.

Risk Evaluation:

No risks associated with the release.

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

The brine water did impact soil.

Action Taken or Planned:

Released water on well site cleaned. residual material in soil that needs to be remediated. Plan in action.

Wastes Disposal Location: A proper disposal facility will be determined.

Agencies Involved: NDDDES, NDIC

Updates

Date: 2/27/2015

Status: Reviewed; Followup Required

Staff: Espe, Brady

Updated Volume:

Notes:

This was also reported in the oil field incidents as number 20150227112921.

Date: 2/27/2015

Status: Phone/Email Contact

Staff: O'Gorman, Brian

Updated Volume:

Notes:

Spoke with the responsible party to determine type of site and type of containment. According to the responsible party, the release was on an injection well site and was contained within the tank's secondary containment. He also mentioned that an inspector from Oil and Gas had been on site for the cleanup and remediation. Spoke with Oil and Gas and confirmed inspector was on site. NDIC retains oversight.